



**RECORD OF EQUIPMENT OF RADIO FACILITIES FOR
COMPLIANCE WITH THE INTERNATIONAL CONVENTION
FOR THE SAFETY OF LIFE AT SEA , 1974, MODIFIED BY
THE PROTOCOL OF 1988 RELATING THERETO
(Form R)**

No HBR0/VHA/20110404142543

This Record shall be permanently attached to the Cargo Ship Safety Radio Certificate

1. Particulars of ship

Name of Ship : KONINGIN JULIANA
BV Register : 33V254
Distinctive number or letters : J8B4312 10785
Minimum number of persons with required qualifications to operate the radio installations : 2 (two)

2. Details of radio facilities

Item	Actual provision
1 Primary systems	
1.1 VHF radio installation :	
1.1.1 DSC encoder	YES
1.1.2 DSC watch receiver	YES
1.1.3 Radiotelephony	YES
1.2 MF radio installation :	
1.2.1 DSC encoder	YES
1.2.2 DSC watch receiver	YES
1.2.3 Radiotelephony	YES
1.3 MF/HF radio installation :	
1.3.1 DSC encoder	-
1.3.2 DSC watch receiver	-
1.3.3 Radiotelephony	-
1.3.4 Direct-printing telegraphy	-
1.4 INMARSAT ship earth station	YES
2 Secondary means of alerting	-
3 Facilities for reception of maritime safety information	
3.1 NAVTEX receiver	YES
3.2 EGC receiver	YES
3.3 HF direct-printing radiotelegraph receiver	-
4 Satellite EPIRB	
4.1 COSPAS-SARSAT	-
4.2 INMARSAT	-
5 VHF EPIRB	-
6 Ship's search and rescue locating device	YES
6.1 Radar search and rescue transponder (SART)	YES
6.2 AIS search and rescue transmitter (AIS-SART)	-

RECORD FORM R No : HBR0/VHA/20110404142543
NAME OF SHIP : KONINGIN JULIANA
BV REGISTER : 33V254

3. Methods used to ensure availability of radio facilities (regulations IV/15.6 and 15.7)

- 3.1 Duplication of equipment : -
3.2 Shore-based maintenance : YES
3.3 At-sea maintenance capability : -

THIS IS TO CERTIFY that this Record is correct in all respects.

Issued at Cuxhaven, on the 5 April 2011

BUREAU VERITAS

Volker Härtle

Volker Härtle
By Order of the Secretary

